

(SUBMIT IN TRIPLICATE)

Land Office Las Cruces
Lease No. 060422
Unit P.A. BOWEN

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 12, 1946

Well No. 1 is located 660 ft. from N line and 660 ft. from W line of sec. 28

R4/4 R4/4 Sec. 28 17E 32E N.M.P.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

East Lusk Lee New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3573 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well plugged and abandoned. Bottom cement plug set from total depth of 2762' back to 2730', 37' above 5 1/2" casing shoe. Plug set 72 hours and bottom fluid found to be shut off. Cut and pulled 5 1/2" casing from 2230'. Mudded hole and set 10 sack cement plug on bridge at 800' in 8 5/8" casing. Cut and pulled 8 5/8" casing from 100' and set 10 sack cement plug and set at surface with 4" by 10' steel marker.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company CULBERTSON & IRWIN, INC.

Address Box 1071

Midland, Texas

By [Signature]

Title President