

Submit 3 Copies To Appropriate District  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
811 South First, Artesia, NM 87210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. <b>30-025-01340</b>
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator <b>Cross Timbers Operating Company</b>		6. State Oil & Gas Lease No. <b>E-398</b>
3. Address of Operator <b>3000 N. Garfield, Suite 175 Midland, Texas 79705</b>		7. Lease Name or Unit Agreement Name: <b>State BY</b>
4. Well Location Unit Letter <b>I</b> : <b>660</b> feet from the <b>East</b> line and <b>1980</b> feet from the <b>South</b> line Section <b>32</b> Township <b>T17S</b> Range <b>R33E</b> NMPM <b>1ea</b> County <b>NM</b>		8. Well No. <b>3</b>
10. Elevation (Show whether DR, RKB, RT, GR, etc.) <b>GR 4035'</b>		9. Pool name or Wildcat <b>Corbin (Queen)</b>

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b> PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>	<b>SUBSEQUENT REPORT OF:</b> REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <b>Mechanical Integrity Test</b> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

3/23/01 MI & RU well service unit.

3/27/01 PU 7" CIBP and set @ 3,770'. MIRU pump truck. Circ hole w/pkr fluid. Pressure tested TCA w/500 psig. Pressure increased to 600 psig in 22 minutes. Loaded hole w/31 bbls pkr fluid. Press tsted TCA @ 540 psig, held for 30 minutes, OK. OCD notified but test was not witnessed. Original chart attached. Request T.A. status for well.

This Approval of Temporary  
Abandonment Expires 4/4/2006

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Janice Courtney TITLE Regulatory Tech DATE 3/30/2001

Type or print name Janice Courtney Telephone No. 915/682-8873  
(This space for State use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
Conditions of approval, if any:

