

(SUBMIT IN TRIPLICATE)

Land Office **Las Cruces**Lease No. **06-967**

Unit _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

RECEIVED

FEB 7 1963

APPROVED
FEB 5 1963
A. R. BRUNK
ACTING DISTRICT ENGINEER

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Artesia, N. M. October 31st, 1962

yatt- hillside

Well No. **5** is located **990** ft. from **[N]** line and **1650** ft. from **[E]** line of sec. **33**Twp. **33**
(1/4 Sec. and Sec. No.)**17**
(Twp.)**33**
(Range)**E**
(Meridian)**El Jamar**
(Field)**Doña Ana**
(County or Subdivision)**New Mexico**
(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

In reply to your request for delinquent report dated 10/30/62, we submit the following information as to the abandonment of well: Application to plug well dated 10/27/59, approved 11/5/59.

Well plugged as follows: set cement plug with bailer from 3571' to 3591'; attempted to break off casing at 3000', failed to pull, tried to circulate free but failed out of collar at 2815'. Set 2" tubing and filled hole with heavy mud and set cement plug as follows: 2025' to 1950'; 1540' to 1465'; 1240' to 1165'. Cased 150' of 7" casing and 410' of 2 5/8" casing, filled with heavy mud and set regulation marker in 11' of cement at surface. Work was completed November 24, 1959 by Archie Casing Rulers.

I understand that this plan of work must receive approval in writing by the Geologist

Company **A. R. Brunk, et al**Address **Box 565, Artesia, New Mexico**

By _____

Title **CO-ORDER**

ILLEGIBLE

APR 30 1963