



(SUBMIT IN TRIPLICATE)  
UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office **New Mexico**  
Lease No. **LC 062004**  
Unit **G**

**RECEIVED**

MAR 6 1963

**D. C. C.**

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	X
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**Ohle - Jones**

**February 19**

**1963**

Well No. **3** is located **2310** ft. from **{N}** line and **1650** ft. from **{E}** line of sec. **30**

**SW NE 30** **17 S** **33E** **NMP**  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
**Mallam** **Lee** **New Mexico**  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **4061** ft.

**DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

**This well was shut-in June, 1960 and is temporary shut -in, waiting on orders.**

**RECEIVED**  
**FEB 20 1963**  
**U. S. GEOLOGICAL SURVEY**  
**ARTESIA, NEW MEXICO**

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Corper Drilling Company, Inc.**

Address **200 Corper Building**  
**Artesia, New Mexico**

By **J. Marshall Smith**

Title **Exec. Vice-President**