



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office _____
Lease No. LD 061276
Unit _____

SEP 21 1961

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 1 is located 1930 ft. from N line and 660 ft. from W line of sec. 19

SE 19 (4 Sec. and Sec. No.) 18 (Twp.) 33 (Range) 13 (Meridian)

SILDOAT (Field) LEA (County or Subdivision) NEW MEXICO (State or Territory)

The elevation of the derrick floor above sea level is 3505 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

LOADED 1 3/4" WITH HEAVY DRILLING MUD. SET CEMENT PLUGS AT FOLLOWING INTERVALS WITH NUMBER OF SACKS AND TYPE CEMENT AS INDICATED:
PLUS #1 : 4600 - 4490 w/ 33 SX TRINITY COMMON; PLUS #2 : 4003 - 3993 w/ 33 SX TRINITY COMMON; PLUS #3 : 2879 - 2569 w/ 33SX TRINITY COMMON; PLUS #4 : 1427 - 1320 w/ 55 SX TRINITY COMMON; PLUS #5 : 265 - 165 w/ 76 SX TRINITY COMMON; CEMENTED 4' MONUMENT WITH 10 SX.

LAST PLUS DOWN AT 11:35 AM, MST, APRIL 10, 1961. WELL PLUGGED AND ABANDONED.

APR 12 1961

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company W. L. BAKER OIL COMPANYAddress P. O. DRAVER 351LIDLAND, TEXAS

By

A. M. Ward Jr.
A. M. WARD, JR.
GEOLOGIST

Title