

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TR (CATE)
(Other instruct on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

N. M. 020343-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

USA Hanson Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Querecho Plains Yates

11. SEC. T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 35 - 18S - 32E

12. COUNTY OR PARISH

Lea

13. STATE

N. Mex.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Hanson Oil Corporation

3. ADDRESS OF OPERATOR

P. O. Box 1515, Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FSL & 660' FWL

Sec. 35, T-18-S, R-32-E, N.M.P.M.

Lea County, New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3708' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD @ 4077' PBSD @ 3720' Perfs. @ 3344-3678' 8-5/8" @ 1419' w/625 sx.
5-1/2" @ 3810' w/250 sx.

The captioned well was plugged and abandoned in the following manner:

1. The hole was displaced with heavy mud.
2. A 25 sx. cmt. plug was spotted across perfs. @ 3268-3368'.
3. The 5-1/2" csg. was cut and recovered from 2610'.
4. A 25 sx. cmt. plug was spotted in-and-out of 5-1/2" csg. stub at 2560-2660'.
5. A 25 sx. cmt. plug was spotted in-and-out of 8-5/8" shoe at 1369-1469'.
6. A 10 sx. cmt. plug was spotted at the surface and a regulation dry hole marker erected.
7. The location was cleaned-up and made ready for final U.S.G.S. inspection on 10-1-70.

RECEIVED

JAN 12 1971

U. S. GEOLOGICAL SURVEY

18. I hereby certify that the foregoing is true and correct

SIGNED

Harry P. Schram

TITLE

Exec. Vice Pres.

DATE 10-9-70

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

JUN 25 1971

ARTHUR R. BROWN
DISTRICT ENGINEER

DATE

*See Instructions on Reverse Side

RECEIVED

JUN 23 1971

**OIL CONSERVATION COMM.
HOBBS, N. M.**