


(SUBMIT IN TRIPLICATE)

U. S. Land Office **Las Cruces**

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Lease or permit No. **029850**



SUNDRY NOTICES AND REPORTS ON WELLS **WELLS OFFICE**

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

L. E. Elliott (a) **Midland, Texas, May 4th** 19**40**

Well No. **1** is located **660** ft. from **W** line and **1930** ft. from **E** line of sec. **11**

SE-1/4 of Sec. 11 **T-20S** **R-34-E** **N.M.P.M.**

North Lynch **Lee County** **New Mexico**

The elevation of the ~~surface~~ **ground** above sea level is **3659** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

~~T.D. 275' - Red Beds.~~ **T.D. 275' - Red Beds.**

Set & cemented 239' of 15-1/2" casing @ 254' with 200 sacks cement. Completed cementing at 12:35 AM 5-1-40.

Drilled plug 1:00 AM 5-4-40. Bailed hole dry and let stand one hour. Tested OK

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **THE TEXAS COMPANY**

Address **Box 1270**

Midland, Texas

By *[Signature]*
Title **District Superintendent**

FDGJr-JSD 5-4-40
USGS-Roswell (3) NMOC (1)