


COPIES OFFICE COPY

Budget Bureau No. 42-R358.4  
Approval expires 12-31-60.

Form G-381a  
(Feb. 1951)



(SUBMIT IN TRIPLICATE)  
UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office \_\_\_\_\_  
Lease No. N.M. 06572  
Unit \_\_\_\_\_

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 23, 1957

Well No. 1 is located 660 ft. from North line and 1000 ft. from West line of sec. 14

S 1/4 Sec. 14 20S 34E N.M.P.M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Undesignated Lea New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3661 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drugged and Abandoned 1-8-57

*2/1/57 Inspector Johnston  
OK*

Spotted 25 sks. 3255'  
25 sks. 1700'  
25 sks. 330'

Appropriate 4' marker and cement plug placed in top of 8 5/8" surface

*Sent to ops. 1 extra copy of report 1/27*

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Albert Gackle, Operator

Address Box 2076

Hobbs, New Mexico

By Paul S. Johnston

Title Superintendent of Production