

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well gas well other SWDW

2. NAME OF OPERATOR
Roger O. Goza

3. ADDRESS OF OPERATOR PO Box 1313
Monahans, Texas 79756

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: SE4 SW4 Sec 22 T20S R34E
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH: same 1989w 660/8

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:		SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF	<input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>	<input type="checkbox"/>
(other) <u>Moved packer</u>		

5. LEASE <u>NM-082(29-000082)</u>	
6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
7. UNIT AGREEMENT NAME	
8. FARM OR LEASE NAME <u>D & E Federal</u>	
9. WELL NO. <u>1</u>	
10. FIELD OR WILDCAT NAME <u>Lynch-Yates SR</u>	
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>Sec 22 T20S R34E</u>	
12. COUNTY OR PARISH <u>Lea</u>	13. STATE <u>NM</u>
14. API NO.	
15. ELEVATIONS (SHOW DF, KDB, AND WD) <u>3675 GR</u>	

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well was pulled and the packer was reset at 3315'. The packer was originally set at 3376'. A mechanical integrity test was conducted on 12/16/88 and passed. The test was witnessed by Eddie W. Seay of the NMDCD.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Roger O Goza by lgjy TITLE Operator DATE 12/20/88

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

R B

RECEIVED

DEC 22 1966

OCD
MOBBS OFFICE