



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **New Mexico**
Lease No. **066126**
Unit **Cross No. 1**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 25, 1957

Well No. **1** is located **330** ft. from **N** line and **330** ft. from **W** line of sec.**34 26**
(Twp. and Sec. No.)**205**
(Twp.)**11E**
(Range)**-**
(Meridian)**Lynch**
(Field)**Lee County**
(County or Subdivision)**New Mexico**
(State or Territory)The elevation of the derrick floor above sea level is **4411** ft. **will be furnished later.**

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded well 3-19-57. Drilled with rotary tools 12 1/4" hole to 156', reduced to 7 7/8" to 400'. Reamed to 12 1/4" to 171'. Cased 8 5/8" cas; at 171' w/125 sz reg. Cnt circ. Job complete 3-20-57. Tested cag w/1000# for 30 min. No pressure losses.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Phillips Petroleum Company**Address **Box 2105, Hobbs, New Mexico**By **W. G. Croston**Title **Dist. Chief Clerk**