

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY Gulf Oil Corporation Box 2167, Hobbs, New Mexico
(Address)

LEASE Lee State "AQ" WELL NO. 1 UNIT A S 32 T 19-s R 35-E

DATE WORK PERFORMED Dec 18-22, 1958 POOL Undesignated

This is a Report of: (Check appropriate block) Results of Test of Casing Shut-off
 Beginning Drilling Operations Remedial Work
 Plugging Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

Kirklin Drilling Company spudded 12-1/4" hole 6:00 PM 12-18-58.

Ran 7 jts (289') 8-5/8" OD 24# J-55 casing. Set and cemented at 301' with 200 sacks regular Neat cement. Plug at 275'. Maximum pressure 150#. Circulated approximately 25 sacks cement. Job complete 6:30 AM 12-21-58.

After waiting over 24 hours, tested 8-5/8" casing with 1000# for 30 minutes. No drop in pressure. Drilled cement plug from 275' to 301' and tested below casing shoe with 400# for 30 minutes. No drop in pressure.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____

Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____

Perf Interval (s) _____

Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

BEFORE AFTER

| | | |
|---------------------------------|-----------------|-------|
| Date of Test | _____ | _____ |
| Oil Production, bbls. per day | _____ | _____ |
| Gas Production, Mcf per day | _____ | _____ |
| Water Production, bbls. per day | _____ | _____ |
| Gas-Oil Ratio, cu. ft. per bbl. | _____ | _____ |
| Gas Well Potential, Mcf per day | _____ | _____ |
| Witnessed by _____ | _____ (Company) | |

OIL CONSERVATION COMMISSION

Name [Signature]
Title _____
Date _____

I hereby certify that the information given above is true and complete to the best of my knowledge!

Name [Signature]
Position Asst. Area Production Supt.
Company Gulf Oil Corporation