

(SUBMIT IN TRIPLICATE)

Land Office New Mexico

Lease No. 04778-A

Unit U.S.A. West Monument

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 31, 1951

Well No. 1 is located 660 ft. from N line and 660 ft. from W line of sec. 23  
C/MW/4 NW/4, Sec. 23 20-S 35-E N.M.P.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Wildcat Lea County New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

103' - Total Depth - Red Bed. Tested 10-3/4" casing & connections with 1000# for 1/2 hour - no pressure drop. After waiting on cement for 24 hours drilled out cement from 86' to 98'. Tested 10-3/4" casing & connections with 1000# for 1/2 hour - no pressure drop. Started drilling formation and 9-7/8" hole at 11:00 A.M., 3-30-51.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Amerada Petroleum Corporation

Address Drawer D

Monument, New Mexico

By [Signature]

Title Assistant District Superintendent