

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Resler and Sheldon		Address 302 Carper Bldg., Artesia, New Mexico				
Lease Smith	Well No. 2	Unit Letter K	Section 34	Township 19N	Range 36E	
Date Work Performed November 28, 1959	Pool Bumont			County Lea		

THIS IS A REPORT OF: (Check appropriate block)

- Beginning Drilling Operations
 Casing Test and Cement Job
 Other (Explain):
 Plugging
 Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Washed well out to original T. D. of 3980'. Ran gamma-neutron log. Fractured down casing w/ 20,000 lbs. sand in water. Then sanded off lower formation. Perforated 3799 to 3779 w/ 40 holes. Fractured w/ 12,000 lbs. sd. in water. Cleaned out to bottom. Ran tubing and rods and put well on pump.

Witnessed by	Position	Company
--------------	----------	---------

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D 3980	P B T D	Producing Interval 3903-3980	Completion Date 9-27-54
Tubing Diameter 2	Tubing Depth 3900	Oil String Diameter 5 1/2	Oil String Depth 3903	
Perforated Interval(s)				
Open Hole Interval 3903-3980		Producing Formation(s) Queen		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover	Nov. 1959	10	50	10	5000	
After Workover	12-15-59	20	100	10	5000	

OIL CONSERVATION COMMISSION		I hereby certify that the information given above is true and complete to the best of my knowledge.				
Approved by <i>[Signature]</i>		Name Vilas P. Sheldon				
Title <i>[Signature]</i>		Position Partner				
Date <i>[Signature]</i>		Company Resler and Sheldon				