

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

and Office **Las Cruces**

Lease No. **080113-1**

Unit **N.M.P.U.**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Reed **2-3 75**

Hobbs, New Mexico January 3, 1945

Well No. **5** is located **2310** ft. from **N** line and **230** ft. from **E** line of sec. **3**

NE/4 Sec. 3
(4 Pct. and Sec. No.)

20-3
(Twp.)

36
(Range)

N.M.P.U.
Meridian

Reed
(Field)

Lee
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings. Indicate mudding jobs, cementing points, and all other important proposed work.

This well has been plugged and abandoned using the following procedure:

The well had already been plugged back to 3770'. - 1831' 5" of 5 1/2" casing were recovered and then plugged back inside 5 1/2" casing with 12# mud and set a cement plug at the top of the 5 1/2" casing left in the hole. Then plugged back to the bottom of the 7-5/8" casing set at 1301' with 12# mud and set a cement plug at the bottom of this casing. 27'0" of 7-5/8" casing was recovered and then plugged back inside this casing with 12# mud and set a cement plug at the top of the 7-5/8" casing left in the hole. Then plugged back with mud to the bottom of the 10-3/4" casing set at 276' and plugged back to surface with cement. A marker was erected and the location restored to its original condition.

I understand the work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Continental Oil Company**

Address **Box 6**

Hobbs, N.M.

[Signature]

ILLEGIBLE

Dist. **sup.**