

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.  
30-025-05576

5. Indicate Type of Lease  
STATE  FEE

6. State Oil & Gas Lease No.  
A-1118 B-1431

7. Lease Name or Unit Agreement Name

STATE EU GAS COM.

8. Well No.  
1

9. Pool name or Wildcat  
EUMONT YATES 7 RV  - PRORATED GAS

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT'  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL  GAS WELL  OTHER

2. Name of Operator  
AMERADA HESS CORPORATION

3. Address of Operator  
DRAWER D, MONUMENT, NEW MEXICO 88265

4. Well Location  
Unit Letter G : 1650 Feet From The NORTH Line and 1650 Feet From The EAST Line  
Section 8 Township 19S Range 37E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
DF 3706'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: <u>CI PENDING PIPELINE CONNECTION</u> <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-19-93  
PULLED TBG & PKR. FOUND TBG. PLUGGED W/IRON SULFIDE FR. 1440' - 1590' & 3700' - 3769'. LEFT 3' OF BOTTOM JT. OF 2-3/8" TBG & 4' PERFORATED SUB IN WELL. TIH W/OVERSHOT & ATTEMPTED TO FISH. UNSUCCESSFUL. TIH W/118 JTS. 2-3/8" TBG & SET OE 3675'. SWABBED WELL. LOWERED TBG TO 3737'. LEFT WELL FLOWING TO TEST TANK. WELL CLOSED IN PENDING PIPELINE CONNECTION.

3-31-93  
FLOWED 44 MCFPD. TP 18#, IN 24 HRS.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Denise Wann TITLE SENIOR PET ENGR DATE 4-5-93

TYPE OR PRINT NAME DENISE WANN TELEPHONE NO. (505) 393-214

(This space for State Use)

APPROVED BY WILEY SEXTON TITLE DISTRICT SUPERVISOR DATE APR 12 1993

CONDITIONS OF APPROVAL, IF ANY:

**RECEIVED**

**APR 08 1993**

**OCD HORBS OFFICE**