

HUMBLE OIL & REFINING COMPANY'S  
N. M. State D #8

NE 1/4 of Section 20, Twp 19-South,  
Range 27-East, Lea County, New Mexico.

DEVIATION SURVEY

Acid bottle test at 500' Deviation 1 degree  
Acid bottle test at 1000' Hole straight  
Acid bottle test at 2000' Hole straight  
Acid bottle test at 2500' Hole straight  
Acid bottle test at 3000' Hole straight

DRILL STEEL TESTS

None.