

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Rev. 11-1-79

WELL NUMBER	
WELL NAME	
WELL TYPE	
WELL STATUS	
WELL LOCATION	
WELL DEPTH	
WELL DIRECTION	
WELL DIRECTION	
WELL DIRECTION	
WELL DIRECTION	

5a. Indicate Type of Lease
State ☐ For ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
SEE APPLICATION FOR PERMIT - 111 (FORM C-101) FOR SUCH PROPOSALS.)

1. GIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Amerada Hess Corporation

3. Address of Operator
Drawer D, Monument, New Mexico 88265

4. Location of Well
UNIT LETTER **G** **1980** FEET FROM THE **North** LINE AND **1980** FEET FROM
THE **East** LINE, SECTION **31** TOWNSHIP **19-S** RANGE **37-E** NMPM.

7. Unit Agreement Name

8. Farm or Lease Name
J. R. Phillips "A"

9. Well No.
3

10. Field and Pool, or Wildcat
Eunice Monument G/SA

11. Elevation (Show whether DF, RT, GR, etc.)
3588' GL

12. County
Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

November 1979 - Pulled rods & pump, checked bottom at 3880', no fill. Pulled tbq. Ran 7-5/8" bit on 2-7/8" tbq. to clean scale, ran pkr. & tbq. & set pkr. at 3806' & tbq. at 3869'. Press. tested tbq., replaced bad jt. & pressure tested OK. Loaded 8-5/8" csg. w/KCl water & pressure tested. Held OK. Spotted 20% acid over Grayburg San Andres zone 8-5/8" csg. perf. fr. 3845' to 3870' and acidized w/6250 gal. 20% NE acid w/additives and 6000 gal. WF30, flushed w/2% KCl water, swabbed load. Pulled tbq. & pkr., re-ran tbq., pump & rods and resumed production.

Test of 12-9-79: Pumped 25 b.o. & 15 b.w. in 24 hrs. on 10-54" SPM.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *E. B. Fisher* TITLE Supv. Adm. Ser. DATE 12-11-79

APPROVED BY *[Signature]* TITLE DATE DEC 14 1979

CONDITIONS OF APPROVAL, IF ANY: