

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease:  
State  Fee   
5. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO CELEPHEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL  GAS WELL  OTHER-  
2. Name of Operator: Marathon Oil Company  
3. Address of Operator: P. O. Box 2409, Hobbs, New Mexico 88240  
4. Location of Well:  
UNIT LETTER L 1653 FEET FROM THE South LINE AND 330 FEET FROM  
THE West LINE, SECTION 5 TOWNSHIP 20S RANGE 37E N.M.P.M.  
15. Elevation (Show whether DF, RT, GR, etc.):  
3575.5' KB

7. Unit Agreement Name  
8. Farm or Lease Name: Bertha Barber  
9. Well No.: 12  
10. Field and Pool, or Wildcat Monument (McKee)  
12. County: Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <u>Squeeze Paddock Oil and Re-test McKee Gas</u> <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Squeezed Paddock oil perforations (5174-5207') using 100 sacks of Class "C" with 3# KCL per sack followed by 75 sacks Class "C" with 3# salt per sack. Would not hold when pressure tested. Re-squeezed using 150 sacks of Class "C" with 3# salt per sack. Tested to 600# for 15 minutes okay. Ran tubing and packer to 9668'. Swabbing failed to unload McKee gas zone (9773-9822') and well is shut in pending additional evaluation.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Mark E Brown TITLE Production Engineer DATE March 6, 1979

APPROVED BY John Runyan TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL: Expires 3/8/80

MAR 8 1979