

OIL CONSERVATION DIVISION

DISTRICT I 1625 N. French Dr., Hobbs, NM 88240
DISTRICT II 811 S. First, Artesia, NM 88210
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410

1220 South St. Francis Dr. Santa Fe, NM 87504

WELL API NO. 30-025-05920
5. Indicate Type of Lease STATE [ ] FEE [x]
6. State Oil / Gas Lease No.
7. Lease Name or Unit Agreement Name North Monument G/SA Unit Blk. 21
8. Well No. 1
9. Pool Name or Wildcat Eunice Monument G/SA
10. Elevation (Show whether DF, RKB, RT,GR, etc.) 3561' GR

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)
1. Type of Well OIL WELL [x] GAS WELL [ ] OTHER Injection Well.
2. Name of Operator Amerada Hess Corporation
3. Address of Operator P.O. Box 840, Seminole, TX 79360
4. Well Location Unit Letter A, 660 Feet From The North Line and 660 Feet From The East Line. Section 5 Township 020S Range 037E NMPM LEA COUNTY
10. Elevation (Show whether DF, RKB, RT,GR, etc.) 3561' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK [ ] PLUG AND ABANDON [ ]
TEMPORARILY ABANDON [ ] CHANGE PLANS [ ]
PULL OR ALTER CASING [ ]
OTHER: [ ]
SUBSEQUENT REPORT OF:
REMEDIAL WORK [x] ALTERING CASING [ ]
COMMENCE DRILLING OPERATIONS [ ] PLUG AND ABANDONMENT [ ]
CASING TEST AND CEMENT JOB [ ]
OTHER: Casing Integrity Test - Continued Injecting. [x]

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
3-21 thru 3-23-2001
MIRU Pool Well Svc. pulling unit. Removed wellhead, installed BOP & TOH w/tbg. & pkr. TIH w/6-1/8" bit to 3825' & TOH. TIH w/7" RBP set at 3694' & press. tested csg. to 500 PSI. Held OK. TOH w/RBP at 3694'. TIH w/7" AD-1 injection pkr. on 2-3/8" tbg. & set pkr. at 3653'. Circ. pkr. fluid. Removed BOP & installed wellhead. Press. tested csg. to 560 PSI for 30 min. Held OK. Chart attached. RDPU & cleaned location. Continued injecting water.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE [Signature] TITLE Bus. Svc. Spec. II DATE 04/04/2001
TYPE OR PRINT NAME Roy L. Wheeler, Jr. TELEPHONE NO. 915-758-6778

(This space for State Use)
APPROVED BY [Signature] TITLE [Signature] DATE [Signature]
CONDITIONS OF APPROVAL, IF ANY:

APR 5 2001

ICS

5

