

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY John Yates Artesia, New Mexico
(Address)

LEASE McClafferty WELL NO. 1 UNIT B S 21 T -19-S R -38-E

DATE WORK PERFORMED February 12, 1958 POOL Undesignated

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☒ Plugging ☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

1. A 25 sx cement plug was placed at Total Depth 4679'.
2. The 5 1/2" casing was shot at 2725' and same amount pulled from the well.
3. A 25 sx cement plug was placed at 2325'.
4. A 15 sx cement plug was placed in bottom of the surface casing.
5. A 10 sx cement plug was placed in top of the hole.
6. A 4" marker complete with necessary information was placed in the top of hole 5' above the ground.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

	BEFORE	AFTER
Date of Test	_____	_____
Oil Production, bbls. per day	_____	_____
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	_____
Gas-Oil Ratio, cu. ft. per bbl.	_____	_____
Gas Well Potential, Mcf per day	_____	_____
Witnessed by _____		

(Company)

OIL CONSERVATION COMMISSION

Name Stanley Saikin
Title _____
Date _____

I hereby certify that the information given above is true and complete to the best of my knowledge. Stanley Saikin
Name Stanley Saikin
Position Yard Superintendent
Company Hobbs Pipe and Supply Company