

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. N/A

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.
N/A

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

1. Type of Well:
OIL WELL GAS WELL OTHER LPG STORAGE

LPG
PROPANE STORAGE WELL

2. Name of Operator
~~WARREN PETROLEUM COMPANY~~ Chevron USA Inc.

8. Well No. 1

3. Address of Operator
P. O. BOX 67, MONUMENT, NEW MEXICO 88265

9. Pool name or Wildcat
N/A

4. Well Location
Unit Letter D : 100 Feet From The NORTH Line and 100 Feet From The WEST Line

Section 1 Township 20S Range 36E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
N/A

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- BRINE PRESSURE TEST (5-29-91 - 6-10-91)
- REMOVED EXISTING WELL HEAD AND TUBING
- RAN LOGS
VERTILOG (6-11-91)
CALIPER SURVEY (6-12-91)
SEGMENTED BOND LOG AND DENSITY SURVEY (6-13-91)
DIRECTIONAL SURVEY (6-14-91)
SONAR SURVEY (6-16-91 - 6-19-91)
- RAN MECHANICAL INTEGRITY TEST (7-10-91 - 7-17-91)
- REPLACED WELL HEAD AND INSTALLED NEW TUBING (4½" AT 1893')

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C. L. Coarsey TITLE PLANT MANAGER DATE 09-19-91

TYPE OR PRINT NAME C. L. COARSEY TELEPHONE NO. 393-2823

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL IF ANY: