


Form 9-331a  
(Feb. 1951)

(SUBMIT IN TRIPLICATE)



UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office \_\_\_\_\_  
Lease No. **LC-066125**  
Unit \_\_\_\_\_

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<b>X</b>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 30, 1963

Well No. **Hanson 17D** **2** is located **330** ft. from **N** line and **1650** ft. from **W** line of sec. **26**

**NR/4 NW/4 Sec. 26** (1/4 Sec. and Sec. No.)      **20 E** (Twp.)      **34 E** (Range)      **10N 23W** (Meridian)  
**Lynch** (Field)      **Lea** (County or Subdivision)      **New Mexico** (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 9/26/63. Cemented 3 5/8" 28# casing at 235 feet with 175 sacks. Cement circulated. Plug down 5:00 PM 9/26/63. WOC 24 hours and pressure tested casing with 600# for 30 minutes, test O.K.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Bark Royalty Company**  
Address **c/o Oil Reports & Gas Services**  
**Box 763**  
**Hobbs, New Mexico**  
By **J. L. Smith**  
Title **Agent**