NUMBER OF COR	HES RECEIVED							•		
1 1 1 1								FORM C-103 (Rev 3-55)		
TRANSPORTER	MISCELLANEOUS REPORTS OF OF CLES.								Ź	
OPERATOR (Submit to appropriate District Office par per Commission 1106)										
Name of Company Address										
Cactus Drilling Company P O Box 1826, Hobbs, New Mexico Well No. Unit Letter Section Township Range Range										
Lease		Ctoto] w		Unit Letter	Section	lownship		Range	
Date Work Pe		3 64 69~	Pool	10		' 31	County	9 6	35 ♦	
4/4/64	& 4/	5/64	Poarl THIS IS A	REPORT O	F: (Check	abbrobria	te block)			
THIS IS A REPORT OF: (Check appropriate block) Casing Test and Cement Job Other (Explain):										
Pluggin	g		Reme	edial Work						
Detailed account of work done, nature and quantity of materials used, and results obtained.										
Well spudded 11:00 AM 4/4/64.										
Drilled 11" hole to depth of 120' and ran 6 joints 8-5/8" 24# casing to depth of 110' set in 75 sx neat cement 2% HA-5. Cement circulated. Waited in cement 24 hours and pressured up on casing to 600# for testing. Pressure held for 30 minute test period logging no drop in pressure. Nippled up and drilling ahead.										
108' casing in hole.										
Witnessed by H. W. Seeley				Position Tool Pusher			Company Cactus Drilling Company			
FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY										
D F Elev. T D PBTD Producing Interval Completion Date										
5 1 5 kev.				I DID			Producing Interval Completion Date			
Tubing Diameter Tubing Dep			Tubing Depth	Oil String Diam			ter Oil String Depth			
Perforated Int	erval(s)				- <u>-</u> -			 		
Open Hole Interval						Producing Formation(s)				
				RESULTS	OF WORK	OVER				
Test		e of	Oil Production BPD		oduction FPD		roduction PD	GOR Cubic feet/B	Gas Well Potential MCFPD	
Before Workover										
After Workover										
I hereby certify that the information given above is true and complete to the best of my knowledge.										
Approved by						Name Cla W. Baker				
Tide Position State of State o						Position Vice President				
Date Hill St. St.						Company Cactus Drilling Company				