

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-23786

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.
E-9122

7. Lease Name or Unit Agreement Name
State "AB"

8. Well No.
1

9. Pool name or Wildcat
Eumont SWD San Andres

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL GAS WELL OTHER SWD

2. Name of Operator
A.A. Oilfield Service Inc.

3. Address of Operator
P O BOX 5208

4. Well Location
Unit Letter C : 660 Feet From The North Line and 1980 Feet From The West Line
Section 3 Township 19S Range 37E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3678 Grd.

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON
TEMPORARILY ABANDON CHANGE PLANS
PULL OR ALTER CASING
OTHER:
SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING
COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
CASING TEST AND CEMENT JOB
OTHER:

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. January 4, 5, & 6, 1995 - Pulled and inspected all collars and pins. Replaced 21 joints of tubing. Picked up 21 joints of new tubing. Ran tubing back in the hole. Set packer with 18 points of tension. Attempted to run casing test and chart meter - would not hold. Pulled tubing and packer out of hole and rigged up Phil's tubing tester. Test packer and tubing back in the hole with 5000 psi. Replaced 11 bad collars. Pumped 50 bbls of packer fluid. Set packer with 18 points of tension. Loaded casing and ran chart meter with 530 psi for 30 minutes - held ok.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE Cyril A. Scheller TITLE Vice President DATE 1-9-95
TYPE OR PRINT NAME Cyril A. Scheller TELEPHONE NO. 392-2577

(This space for State Use)
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JAN 10 1995