

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

COPY TO O. C.

SUBMIT IN TRIPPLICATE
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. NAME OF OPERATOR
Walter W. Krug DBA Wallen Production Company

3. ADDRESS OF OPERATOR
Box 1960, Midland, Texas 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660 FSL & 330 FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
GR 3671

5. LEASE DESIGNATION AND SERIAL NO.

N.M. 070315

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Wallen Bass

9. WELL NO.

3

10. FIELD AND POOL, OR INDICATE
Seven Rivers
Middle Lynch, Yates11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 21, T 20 S, R 34 E

12. COUNTY OR PARISH 13. STATE
Lea New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Liner

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☐
☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

On 1/15/79 at 2:P.M. we cemented 595' of 10.5#,
4½" casing in the above well. We cemented it with
60 sacks of class "c" neat cement. Twenty four(24)
hours later we ran the enclosed temperature log.

RECEIVED
FEB 5 1979
U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

depth 3680'

RECEIVED
JAN 24 1979

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Walter W. Krug

TITLE

Engineer

DATE

1/18/79

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD
FEB 5 1979

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

*See Instructions on Reverse Side

SECRET

APR 1968
MOORE NEW MEXICO