

ATTACHMENT TO FORM C-103
SUNDRY NOTICES AND REPORTS ON WELLS
SHELL STATE #1
330' FNL & 1980' FWL
SECTION 36-22S-32E
LEA COUNTY, NEW MEXICO

WOC. Prep to complete well. RD.

- 1/24/93 RU Fifty-Five Well Service. Drill out DV tool at 5708'. Circulate hole with 2% KCL. TOH with tools. Clean out to 9110'.
- 1/25/93 RU Schlumberger. Run CBL from 9100' to intermediate casing. Good cement. TOH with CBL. RU and TIH with 4" casing guns. Perf (9) .42 holes as follows: 9056'-9058'. TOH with guns. SI and SD.
- 1/26/93 TIH with packer. Acidize perfs 9056'-9058' with 1000 gal 15% NEFE. Swab test.
- 1/27/93 TOH with tools. TIH with RBP. Set RBP at 8920'. Test to 4000#. Held OK. TOH with tubing. RU Schlumberger. Perf (14) .42 holes as follows: 8828'-8838'. TOH with guns. SIH with packer.
- 1/28/93 Set packer at 8714'. RU Halliburton. Acidize with 750 gal 7 1/2% NEFE. Swab test. Frac with 12000 gal 35# X-Link and 23100# 16/30 RC. SI and SD.
- 1/29/93 Open well and flow back. Leave flowing to battery. RD.