UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL

PULL OR ALTER CASING

MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other)

Dec. 19/3		Hudget Bureau No. 42-R1424	
1 2 %	UNITED STATES DEPARTMENT OF THE INTERIOR	5. LEASE NM-2512	
	GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
	Y NOTICES AND REPORTS ON WELLS form for proposals to drill or to deepen or plug back to a differen form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME MFU 8. FARM OR LEASE NAME	
1. oil well	gas other	9. WELL NO.	
	OF OPERATOROX 460, Hobbs, N.M. 88240	10. FIELD OR WILDCAT NAME Hare Simpson 11. SEC., T., R., M., OR BLK. AND SURVEY OR	
below.) AT SURFA	N OF WELL (REPORT LOCATION CLEARLY. See space 17 ACE: 510' FSL & 660' FEL PROD. INTERVAL: L DEPTH:	AREA Sec. 3-215-37E 12. COUNTY OR PARISH 13. STATE LECA NM 14. API NO.	
	PPROPRIATE BOX TO INDICATE NATURE OF NOTICE OR OTHER DATA		
REQUEST FOR	R APPROVAL TO: SUBSECUENT REPORT OF		

(NOTE: Report results of multiple completion or zone

change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

SUBSECUENT REPORT OF:

MIRU. Set pkr @ 7335'. Acidize perfs 7517'-7776' w/4620 gals. 15% HICL-NE-FE. Flush w/ 8190 gals. 2% KCL. Swabbed. Rel pkr @ 7335'. Ran producing equipment SN @ 7490'. Well Temporarily shut-in on 10/20/84.

Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct SIGNED Administrative Supervisor DATE	= 1/3/85
(This space for Federal or State office use)	
APPROVED BY TITLE DATE	ΤΕ

*See Instructions on Reverse Side