



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces

Lease No. 410 0917416 b

Unit Lease

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	Subsequent report of perform to additional pay	<input checked="" type="checkbox"/>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Blank 3-3

March 6, 19 63

Well No. 10 is located 2970 ft. from S line and 1650 ft. from E line of sec. 3
Lot 15
34/4 NE/4 Sec. 3 21-4 37-5 NMFM
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
NMFM Lee New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3480 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

BEFORE WORKOVER: TD 2302 IN, FB 6785, DF 12, ELV 3480, CSD PT 7" AT 8301, PAY DRINKARD 6532-6830. PERP 6660-90, 6720-60. PRIOR TO WORKOVER WELL WAS TBO. WORK DONE: CUT OFF STUCK TBO AT 6730 LEAVING 1 JT TBO, PERP NIPPLE, LEAVING NIPPLE & 6 FT TBO SUB IN HOLE. PERP DRINKARD W/4 SINGLE PLANE HOLES AT 6576, 6584, 6598 & 6612. TRTD 6576-6612 W/1000 GALS ACID, 20,000 GALS SALFAC, 20,000 LBS OF IN 4 STAGES USING 9 BALL CHARGES. AFTER WORKOVER: TD, FB, DF, ELV, CSD PT & PAY SAME AS BEFORE WORKOVER. PERP 6576, 6584, 6598, 6612, 6660-90, 6720-60. PERP 37 BO, NO WTB, W/56.7 WGT IN 24 HRS. OGR 1772. DAILY ALLOW 32 BO. WORKOVER STARTED 2-11-63, COMP 3-4-63, TRTD 3-4-63.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company

Address Box 68

Junice, New Mexico

By SIGNED: J. R. V. [Signature]

Title District Superintendent

LOG-3 LOG-2 4AM FILE

MAN AM, Mm-3 ATL, Hous-2 Calif, Hous, Mid 1 - each