

DUPLICATE

NEW MEXICO OIL CONSERVATION COMMISSION

MISCELLANEOUS REPORTS ON WELLS

US-322

Submit this report in triplicate to the Oil Conservation Commission District Office within ten days after the work specified is completed. It should be signed and filed as a report on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below.

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL	<input checked="" type="checkbox"/>	REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL			

July 6, 1952
Date

Jal, New Mexico
Place

Following is a report on the work done and the results obtained under the heading noted above at the.....

R. Olsen Oil Company Boyd Well No. 1 in the
Company or Operator Lease
SW SW NE of Sec. 23, T. 22S, R. 37E, N. M. P. M.,
Drinkard Pool ea County.

The dates of this work were as follows: 6-9-52 7-3-52

Notice of intention to do the work was ~~received~~ submitted on Form C-102 on May 26, 19 52,
and approval of the proposed plan was ~~received~~ obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Acidized well thru tubing with packer set at 6293'. Used 15,000 gallons
15% SLT acid. Production increased from 9 barrels per day to 20 barrels
per day.

Witnessed by E. D. Watson R. Olsen Oil Company Geological Engineer
Name Company Title

APPROVED:
OIL CONSERVATION COMMISSION

R. J. Blum
Name
Title

Jul 10 1952, 19
Date

I hereby swear or affirm that the information given above
is true and correct.

Name Levey Watson
Position Geological Engineer

Representing R. Olsen Oil Company
Company or Operator

Address Drawer 121 Jal, New Mexico