Form 9-331 a (March 19*2)	والمراجعين
Ç.Ş.	Signaramore Chi
THE STATE OF THE S	and the first the first

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR

Land Office Las Eruces
Lease No. 062334
Unit
PENT

		105 A 195
NOTICE OF INTENTION TO DRILL NOTICE OF INTENTION TO CHANGE PLANS NOTICE OF INTENTION TO TEST WATER S NOTICE OF INTENTION TO RE-DRILL OR F NOTICE OF INTENTION TO SHOOT OR ACIE NOTICE OF INTENTION TO PULL OR ALTER	SUBSEQUE SUB	JENT REPORT OF WATER SHUT-OFF. JENT REPORT OF SHOOTING OR ACIDIZING. JENT REPORT OF ALTERING CASING. JENT REPORT OF REDRILLING OR REPAIR. JENT REPORT OF ABANDONMENT.
		and 1936ft. from Viline of sec. 13
School Sec. 13 (96 Sec. and Sea No.) South Leonard (1956.)	Loa	Nov Mexico
(Field) he elevation of the derrick flo	(County or Subdivision)	
	DETAILS OF W	ORK

July 2, 1950, at 5:30 P.M., 75 hours after being comented, the 10-3/4" casing at 292' was tested for shut-off. Top of cement was found at 282' inside of pipe. Casing test made after bailing dry and allowing to stand 3 hours. No fluid entered. Coment plug drilled to 295 and bailed dry. Stood 3 hours for test and no fluid entered. Casing test and water shut-off test considered satisfactory. Drilled chead with 10" bit.

Company	Leonard Oil Company	
Address	9. 0. Box 872	
	Roswell, New Mexico	By Emmell a While