INCLINATION REPORT

Operator Reserve Oil, Inc.	Address	312 HBF	Building,	Midland,	Texas	7970
Lease Name Cooper Jal Unit	Well No.	153	_ Field _	Langlie M	attix	-
Location Unit "L", 280' FWL & 1400' FS	L, Sec. 19	9, T24S,	R37E, Le	a County. 1	Vew M	exico

Measured Depth (Feet)	Course Length (Feet)	Angle of Inclination (Degrees)	Displacement	Accumulative Displacement
3831	383	1	6.70'	6.70'
820	437	1	7.65'	14.35'
1310	490	3/4	6.421	20.77'
1895	585	3/4	7.66'	28.43'
2331	436	1	7.63'	36.061
2857	526	4	36.66'	72.72'
3115	258	3	13.49'	86.21'
3388	273	1	4.78'	90.99'
3711	323	1 1/2	8.46'	99.45'

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

November 30, 1980

	Camera R. Charle	1 23 79
	Title District Engineer	
Sworn and subscribed to in my prese	ence on this the 23rd day of January	_, 19 <u>79</u> .
My Commission Expires	Notary Public in and for the Count	0-2e
November 30 1080	Notary Public In and for the Count	y of

RESERVE OIL, INC.

Midland, State of Texas