

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 1:22 pm, Jun 13, 2016

Form C-141
Revised August 8, 2011
Should be filed with appropriate local office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	Chevron USA Inc.	Contact	Josepha DeLeon
Address	15 Smith Rd., Midland, TX, 79705	Telephone No.	wk: 575-263-0424 cell: 432-425-1528
Facility Name	VGSAU	Facility Type	Satellite
Surface Owner	N/A	Mineral Owner	State of New Mexico
		API No.	See Attached

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	1	18	34					Lea

NATURE OF RELEASE

Type of Release	Flare	Volume of Release:	92 MCF	Volume Recovered	0mcf
Source of Release	Flare	Date and Hour of Occurrence	06/09/2016 02:06 - 3:46 AM	Date and Hour of Discovery	06/09/2016 6:00 AM
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour:				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.* N/A					
Describe Cause of Problem and Remedial Action Taken.* Flare at VGSAU after Buckeye CO2 Plant lost compression and field pressured up causing VGSAU to vent.					
Describe Area Affected and Cleanup Action Taken.* N/A					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		OIL CONSERVATION DIVISION			
Printed Name: Josepha DeLeon		Approved by Environmental Specialist: 			
Title: HES Compliance Support - Environmental		Approval Date: 06/13/2016		Expiration Date: //	
E-mail Address: jdx@chevron.com		Conditions of Approval: ///		Attached <input type="checkbox"/>	
Date: 06/09/2016		Phone: 432-425-1528		nJXK1616548108	

* Attach Additional Sheets If Necessary

VGSAU API –

VGSAU	300250227101
VGSAU	300250227200
VGSAU	300250227300
VGSAU	300250227400
0064/14029	300250227500
VGSAU	300250227600
VGSAU	300250227700
VGSAU	300253071700
VGSAU	300253071800
0064/14029	300253072100
VGSAU	300253075400
VGSAU	300253075500
VGSAU	300253075600
VGSAU	300253079700
VGSAU	300253080000
VGSAU	300253080100
VGSAU	300253080200
VGSAU	300253080300
0064/14029	300253084300
VGSAU	300253084400
VGSAU	300253085100
0064/Not assigned	300253170900
VGSAU	300253199300
VGSAU	300253200400
VGSAU	300253202801
VGSAU	300253202601
VGSAU	300253650000
VGSAU	300253650001
VGSAU	300250225901
VGSAU	300253075401
VGSAU	300250227201
VGSAU	300250226001
VGSAU	300253862800
VGSAU	300253862700
VGSAU	300253855400