

4441 District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

| | | | |
|---------------------|---|---------------------|-------------------------------------|
| Name of Company | Devon Energy Production Company | Contact | Rebecca Jamison, Production Foreman |
| Address | 6488 Seven Rivers Hwy Artesia, NM 88210 | Telephone No. | 575-513-5538 |
| Facility Name | Rattlesnake 16 SWD 1 | Facility Type | Salt Water Disposal |
| Surface Owner State | Mineral Owner State | API No 30-025-42355 | |

LOCATION OF RELEASE

| | | | | | | | | |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
| E | 16 | 26S | 34E | 2375 | North | 210 | West | Lea |

Latitude: 32.0441688

Longitude: -103.4826937

NATURE OF RELEASE

| | | | | | |
|-----------------------------|---|--|--|----------------------------|---------------------|
| Type of Release | Produced Water (PW) | Volume of Release | 130BBLS | Volume Recovered | 130BBLS |
| Source of Release | Storage tank | Date and Hour of Occurrence | 8/17/2017 @ 9:40 PM | Date and Hour of Discovery | 8/17/2017 @ 9:40 PM |
| Was Immediate Notice Given? | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? | OCD-Olivia Yu BLM-Shelly Tucker | | |
| By Whom? | Rebecca Jamison, Production Foreman | Date and Hour | OCD- 8/08/2017 @ 4:40 PM BLM- 8/10/2017 @ 4:42 PM | | |
| Was a Watercourse Reached? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse | | | |

RECEIVED

By Olivia Yu at 8:22 am, Aug 28, 2017

| | |
|---|---|
| If a Watercourse was Impacted, Describe Fully.* | N/A |
| Describe Cause of Problem and Remedial Action Taken.* | Scada issues misread the tanks and no alarms were sent resulting in the produced water tanks running over. The pumps were shut down into the SWD and proper personnel were contacted. |

| | |
|---|---|
| Describe Area Affected and Cleanup Action Taken.* | Approximately 130BBLS of PW was released as a result of tanks overflowing. Approximately 130BBLS of PW was recovered via the dispatched vacuum truck. All fluid stayed inside the lined SPCC containment. Once fluids were removed the liner was visually inspected by Devon field staff for any pinholes or punctures and none were found. Based on this inspection there is no evidence that the spill fluids left containment. |
|---|---|

| |
|--|
| I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. |
|--|

| | | |
|---------------------------------------|--|-----------------------------------|
| Signature: Dana DeLaRosa | OIL CONSERVATION DIVISION | |
| Printed Name: Dana DeLaRosa | Approved by Environmental Specialist: | |
| Title: Field Admin Support | Approval Date: 8/28/2017 | Expiration Date: |
| E-mail Address: dana.delarosa@dmn.com | Conditions of Approval: | Attached <input type="checkbox"/> |
| Date: 8/9/2017 Phone: 575.746.5594 | Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids. | |

* Attach Additional Sheets If Necessary

nOY1724030412

Rattlesnake 16 SWD 1
130BBLs PW_8.9.2017



This map is for illustrative purposes only and is neither a legally recorded map nor survey and is not intended to be used as one. A person makes no warranty, representation or claim regarding this map.

WGS_1984_Web_Mercator_Auxiliary_Sphere
Prepared by: Dana DeLaRosa
Map is current as of: 24-Aug-2017



Devon_Google_Maps_L
imagery

