

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Production LLC [OGRID] 217955	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077	
Facility Name: GOLDENEYE 18 FEDERAL COM #001	Facility Type: Battery	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-025-39742

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	18	24S	32E	330	South	660	West	Lea

Latitude 32.2110062 Longitude - 103.7208481 NAD83

### NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 13 bbls pw	Volume Recovered: 12 bbls pw
Source of Release: Water Tank	Date and Hour of Occurrence: 10-13-2017 2:00 pm	Date and Hour of Discovery: 10-13-2017 2:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

**RECEIVED**

**By Olivia Yu at 3:19 pm, Oct 16, 2017**



Describe Cause of Problem and Remedial Action Taken.\*

The release occurred when a hole developed in the bottom of the steel water tank. The tank is being repaired.

Describe Area Affected and Cleanup Action Taken.\*

The release occurred within the lined facility. Vacuum trucks were immediately dispatched to recover all standing fluids. Concho will have the spill area evaluated for any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Dakota Neel		Approved by Environmental Specialist: 	
Title: HSE Coordinator	Approval Date: 10/16/2017	Expiration Date:	
E-mail Address: dneel2@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: October 16, 2017 Phone: 575-746-2010	Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.		

\* Attach Additional Sheets If Necessary

**nOY1728955376**