

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production Company	Contact Hub Perry, Production Foreman
Address 6488 Seven Rivers Hwy, Artesia NM 88210	Telephone No. 575-513-9637
Facility Name Thistle Unit 20H	Facility Type Oil

Surface Owner State	Mineral Owner State	API No. 30-025-40015
---------------------	---------------------	----------------------

LOCATION OF RELEASE

Unit Letter D	Section 27	Township 23S	Range 33E	Feet from the 150	North/South Line North	Feet from the 150	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	---------------

Latitude 32.2825584 Longitude -103.5682526 NAD83

NATURE OF RELEASE

Type of Release None	Volume of Release 0bbls	Volume Recovered 0bbls
Source of Release N/A	Date and Hour of Occurrence 11/10/2017 @ 2:30AM MST	Date and Hour of Discovery 11/10/2017 @ 2:30AM MST
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Mike Shoemaker, EHS Professional	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.* N/A

RECEIVED

By Olivia Yu at 10:53 am, Nov 20, 2017

Describe Cause of Problem and Remedial Action Taken.*

The flare scrubber swamped out due to low psi causing a fire at the flare stack. Closed valves on flare meter and pilot supply gas. No fluids released. Fire extinguisher used.

Describe Area Affected and Cleanup Action Taken.*

There was no damage to the tanks. There was no release of any fluids. This report is for information only due to the fire on location.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: Dana DeLaRosa

Approved by Environmental Specialist:

Printed Name: Dana DeLaRosa

Title: Field Admin Support

Approval Date:

11/20/2017

Expiration Date:

E-mail Address: dana.delarosa@dv.com

Conditions of Approval:

Attached ☐

Date: 11/17/2017

Phone: 575.746.5594

* Attach Additional Sheets If Necessary

nOY1732439307

Thistle Unit 20H
Fire_11.10.2017



This map is for illustrative purposes only and is neither a legally recorded map nor survey and is not intended to be used as one. A person makes no warranty, representation or statement of any kind regarding this map.

WGS_1984_Web_Mercator_Auxiliary_Sphere
Prepared by: Dana DeLaRosa
Map is current as of: 15-Nov-2017

