

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating, LLC (OGRID# 229137)	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No.: 432-683-7443
Facility Name: Pintail 3 Federal SWD #001	Facility Type: Tank Battery

Surface Owner: BLM	Mineral Owner: Federal	API No.: 30-025-41208
---------------------------	-------------------------------	------------------------------

LOCATION OF RELEASE

Unit Letter J	Section 3	Township 26S	Range 32E	Feet from the 2500	North/South Line South	Feet from the 1400	East/West Line East	County Lea
-------------------------	---------------------	------------------------	---------------------	------------------------------	----------------------------------	------------------------------	-------------------------------	----------------------

Latitude: 32.07196337 Longitude: -103.6587219 NAD83

NATURE OF RELEASE

Type of Release: Oil & Produced Water	Volume of Release: 3bbls oil & 147bbls PW	Volume Recovered: 2.5bbls oil & 146.5bbls PW
Source of Release: Tank Overflow	Date and Hour of Occurrence: 11/15/2017 10:00am	Date and Hour of Discovery: 11/15/2017 10:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Olivia Yu-NMOCD Shelly Tucker-BLM	
By Whom? Dakota Neel	Date and Hour: 11/15/2017 10:55am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By Olivia Yu at 10:28 am, Nov 20, 2017



Describe Cause of Problem and Remedial Action Taken.*

A stuck float resulted in a tank overflow. The float was repaired.

Describe Area Affected and Cleanup Action Taken.*

All of the fluid remained inside of the lined containment. A vacuum truck was dispatched to recover all freestanding fluids. Concho will have the spill area evaluated for any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Sheldon L. Hitchcock		Approved by Environmental Specialist: 	
Title: HSE Coordinator		Approval Date: 11/20/2017	Expiration Date:
E-mail Address: slhitchcock@concho.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11/16/2017 Phone: 575-746-2010		Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.	

* Attach Additional Sheets If Necessary

nOY1732438128