

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report

☒ Final Report

Name of Company	Devon Energy Production Company	Contact	Matt Nettles, Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No.	575-513-5767
Facility Name	Cotton Draw 32 State 2 SWD	Facility Type	SWD

Surface Owner State	Mineral Owner State	API No	30-025-41524
---------------------	---------------------	--------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	32	24S	32E	1180	South	1000	East	Lea

Latitude: 32.1699175

Longitude: -103.6913616

NATURE OF RELEASE

Type of Release	Produced Water (PW)	Volume of Release	6BBLS PW	Volume Recovered	6BBLS PW
Source of Release	Pin hole in gun barrel drain line	Date and Hour of Occurrence	3/13/2017 @ 1:30AM	Date and Hour of Discovery	3/13/2017 @ 1:30AM
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	N/A		
By Whom?	N/A	Date and Hour	N/A		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	N/A		

RECEIVED

By Olivia Yu at 3:35 pm, Mar 27, 2017

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
A pin hole developed in the gun barrel causing the drain line to release produced water. The tank was isolated to prevent further release. Repairs will be made before equipment is placed back into service. .

Describe Area Affected and Cleanup Action Taken.*
Approximately 6bbbls produced water was released into the lined containment. A vacuum truck was called and recovered 6bbbls produced water from the lined containment. The containment was visually inspected for holes and none were found. No further action is necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Dana DeLaRosa</i>	OIL CONSERVATION DIVISION	
Printed Name: Dana DeLaRosa	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Admin Support	Approval Date: 3/27/2017	Expiration Date:
E-mail Address: Dana.DeLaRosa@dmv.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3.27.2017 Phone: 575.746.5594	Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.	

* Attach Additional Sheets If Necessary

Cotton Draw 32 State 2 SWD
6BBL5 PW_3.13.2017



This map is for illustrative purposes only and is neither a legally recorded map nor survey and is not intended to be used as one. No warranty is made or shall be made by or for any kind regarding this map.

WGS_1984_Web_Mercator_Auxiliary_Sphere
Prepared by: Dana DeLaRosa
Map is current as of: 13-Mar-2017



S32.T24S.R32E

