

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Marathon Oil Permian LLC	Contact: Raquel Chacon	
Address: 5555 San Felipe St., Houston, TX 77056	Telephone No.: 281-910-0441	
Facility Name: RUSTY ANCHOR 7 FEDERAL COM #001H	Facility Type: Oil Well	
Surface Owner: Federal	Mineral Owner: Federal	API No.: 30-025-43240

LOCATION OF RELEASE

Unit Letter M	Section 07	Township 20S	Range 33E	Feet from the 420	North/South Line FSL	Feet from the 996	East/West Line FWL	County Lea
------------------	---------------	-----------------	--------------	----------------------	-------------------------	----------------------	-----------------------	---------------

Latitude 32.58160463 Longitude -103.707935 NAD83

NATURE OF RELEASE

Type of Release: Crude Oil	Volume of Release:	Volume Recovered:
Source of Release: Flare	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery: 11/19/2017: 0900 hrs
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Shelly Tucker BLM (Email), Olivia Yu OCD (Email)	
By Whom? Raquel Chacon	Date and Hour: 11/20/2017 0753 HRS	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By Olivia Yu at 8:58 am, Dec 07, 2017


Describe Cause of Problem and Remedial Action Taken.*

As a result of a vessel overloading, fluid was sent to flare causing a small fire. Fire was on location and well was shut down for repair. The fire self-extinguished. The well was shut in pending further investigation.

Describe Area Affected and Cleanup Action Taken.*

Approximately 8'X 10' area around the flare. The contaminated soil has been removed and disposed of appropriately.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Raquel Chacon</i>		OIL CONSERVATION DIVISION	
Printed Name: Raquel Chacon		Approved by Environmental Specialist: 	
Title: HES Professional	Approval Date: 12/7/2017	Expiration Date:	
E-mail Address: rchacon@marathonoil.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 12/04/2017	Phone: 281-910-0441		

* Attach Additional Sheets If Necessary

nOY1734132118



