

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Caza Operating LLC	Contact Tony Sam	
Address 200 N. Lorraine St. #1550, Midland, TX 79701	Telephone No. 432-682-7424	
Facility Name Eagleclaw Federal 1H	Facility Type Battery	
Surface Owner	Mineral Owner	API No. 30-025-42988

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	5	20S	35E	190	north	467	west	Lea

Latitude 32° 36' 32.62" Longitude -103° 29' 11.6"

NATURE OF RELEASE

Type of Release oil and water	Volume of Release 2bbls	Volume Recovered 2bbls
Source of Release transfer hose	Date and Hour of Occurrence 11/24/17 17:00	Date and Hour of Discovery 11/24/17 17:00
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

APPROVED

By Olivia Yu at 9:47 am, Jan 02, 2018



Describe Cause of Problem and Remedial Action Taken.*

Fluid was being transferred to the treater. The hose coupling leaked. Transfer was shut down and the coupling connection was repaired.

Describe Area Affected and Cleanup Action Taken.*

The leak was caught by the secondary containment and the a vac truck was used to clean up the leaked out oil and water. The affected area was steam cleaned and then vacuumed again. The liner inspection was good and no breach detected. Disposal of fluids was at a commercial facility.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Steve Morris	Approved by Environmental Specialist: 	
Title: Contract Engineer	Approval Date: 1/2/2018	Expiration Date: xx/xx/xxxx
E-mail Address: steve.morris@mojoenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/29/2017	Phone: 403-923-9750	

* Attach Additional Sheets If Necessary

nOY1734129187









