

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: <b>COG Operating, LLC (OGRID# 229137)</b>	Contact: <b>Robert McNeill</b>	
Address: <b>600 West Illinois Avenue, Midland TX 79701</b>	Telephone No.: <b>432-683-7443</b>	
Facility Name: <b>Macho Nacho 7 State SWD #001</b>	Facility Type: <b>Tank Battery</b>	
Surface Owner: State	Mineral Owner: State	API No.: 30-025-42463

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	7	24S	33E	2000	North	2200	West	Lea

Latitude: 32.234001151 Longitude: -103.61263191 NAD83

### NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 14bbls	Volume Recovered: 14bbls
Source of Release: Tank Overflow	Date and Hour of Occurrence: 2/10/2018 9:30am	Date and Hour of Discovery: 2/10/2018 9:30am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A third party truck driver overflowed a produced water tank due to human error.

Describe Area Affected and Cleanup Action Taken.\*

All of the fluid remained inside of the lined containment. A vacuum truck was dispatched to recover all freestanding fluids. Concho will have the spill area evaluated for any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

### OIL CONSERVATION DIVISION

Signature: *Sheldon Hitchcock*

Printed Name: Sheldon L. Hitchcock

Title: HSE Coordinator

E-mail Address: slhitchcock@concho.com

Date: 2/13/2018

Phone: 575-746-2010

Approved by Environmental Specialist:

Approval Date:

2/14/2018

Expiration Date:

Conditions of Approval:

Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.

Attached ☐

\* Attach Additional Sheets If Necessary

nOY1804546888

**RECEIVED**

**By Olivia Yu at 11:43 am, Feb 14, 2018**