<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141

Revised April 3, 2017

Release Notification and Corrective Action

						OPERA:				ıl Report	\boxtimes	Final Rep	port
			ion Company		Contact Wesley Ryan, Production Foreman								
		Rivers Hwy	NM 88210		Telephone No. 575-390-5436								
Facility Name Cotton Draw Unit 237H						Facility Type Oil							
Surface Ow	ner Feder	al	Mineral C	wner F	r Federal API No. 30-025-41996								
Surrace S II	101 1 0001	<u>w1</u>		'		N OF REI	LEASE		111110				
Unit Letter	Section	Township	Range	Feet from the		South Line	Feet from the	East/West Line		County			
M	10	25S	32E							Lea			
			I	Latitude_ 32.137	93_ L o	ngitude_10	3.66862_ NAD	83					
				NAT	URE	OF RELI	EASE						
Type of Release						Volume of Release			Volume Recovered				
Produced Water						6bbls Data and Have of Occurrence			6bbls Date and Hour of Discovery				
Source of Release Water tank						Date and Hour of Occurrence February 4, 2018 @ 11:00 AM			February 4, 2018 @ 11:00 AM MST				
						MST				, 2 010 0 11100 1211 1121			
Was Immediate Notice Given?						If YES, To Whom?							
☐ Yes ☐ No ☒ Not Required													
By Whom? N/A						Date and Hour N/A							
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse. N/A							
						14/11	DECEIL	/ED					
If a Watercourse was Impacted, Describe Fully.* N/A						RECEIVED							
1 \ / A							By Olivia	a Yu a	t 1:27	' pm, F	eb 1	<i>6, 201</i>	8
		em and Reme											
A 3 inch vict	aulic fitting	was leaking a	at the wate	er production tank.	. The w	ell was shut i	n and the tank wa	as isolated	l to stop th	ne release.			
Describe Are	a Affected	and Cleanup A	Action Tal	ken.*									
				eased into the line	d SPCC	containment	ring. A vacuum	truck was	dispatche	ed and recov	ered aj	proximate	ly
				t. All fluid stayed									
			any pinh	oles or punctures	s and no	one were for	und. Based on tl	his inspe	ction the	re is no evi	dence	that the	
spill fluids l	left contair	iment.											
I hereby certi	ify that the	information gi	iven above	e is true and comp	lete to th	ne best of my	knowledge and u	ınderstand	d that purs	uant to NM	OCD rı	ıles and	
regulations a	ll operators	are required t	o report a	nd/or file certain r	elease n	otifications a	nd perform correc	ctive actio	ons for rele	eases which	may er	ndanger	
				ce of a C-141 report investigate and re									
				otance of a C-141									•
		ws and/or regu			•		•	1		•			
						OIL CONSERVATION DIVISION							
Signature: Sheila Fisher										(9)1			
-						Approved by Environmental Specialist:							
Printed Name	e: Sheila Fi	sher				прриотеа ој	2.1711 omnentar 5	pecianst.					
Title: Field Admin Support						Approval Date: 2/16/2018 Expiration Date:							
•													
E-mail Address: Sheila.Fisher@dvn.com Date: 2/16/18 Phone: 575.748.1829					_	Conditions of Approval:				Attached			
					- 11	Please inspect liner in question. Provide							
Attach Additional Sheets If Necessary						NMOCD with a concise report of the							
,						inspection with affirmation the liner has					718816	\neg	
				1 -	and will car	atiniia ta cant	ain liairi	ıdc		ししナ /	TOO 10		

Cotton Draw Unit 237H 6bbls pw_2.4.18 This map is for illustrative purposes only and is interested in magnetic and purpose only and is not intended to be used as one. Devon makes not intended to be

