

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company EOG Y Resources, Inc.	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 th Street	Telephone No. 575-748-1471	
Facility Name Atoka Bank & Heartthrob Battery	Facility Type Battery	

Surface Owner State	Mineral Owner State	API No.
------------------------	------------------------	---------

LOCATION OF RELEASE

Unit Letter	Section 17	Township 24S	Range 33E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
-------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 130 B/PW	Volume Recovered 129 B/PW
Source of Release 3' water fill line	Date and Hour of Occurrence 1/10/2017; AM	Date and Hour of Discovery 1/10/2017; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kristen Lynch & Tomas Oberding/NMOCD I	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 1/11/2017; AM (Email)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A 3" water line from the heater treater developed a hole, causing the release. Vacuum truck(s) and roustabout crews were called.



Describe Area Affected and Cleanup Action Taken.*

An approximate area of 20' X 25' and 30' X 50' within the lined/bermed battery. Vacuum truck recovered 129 bbls of the released produced water (99%), the remaining produced water was removed with the gravel (gravel disposed at an NMOCD approve facility). The water line was repaired. **Depth to Ground Water: 50-99' (approximately 50', per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10. Based on the battery being lined/bermed, repairs made and 99% released produced water recovered, EOG Resources, Inc. requests closure.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

RECEIVED

By Olivia Yu at 2:45 pm, Mar 01, 2017

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Approved by Environmental Specialist: 	
Title: Environmental Supervisor	Approval Date: 3/1/2017	Expiration Date:
E-mail Address: Robert_Asher@eogresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: January 19, 2017 Phone: 575-748-4217	Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.	

* Attach Additional Sheets If Necessary

From: [Yu, Olivia, EMNRD](#)
To: [Bob Asher](#)
Cc: ["agroves@slo.state.nm.us"](mailto:agroves@slo.state.nm.us)
Subject: RE: Form C-141, Initial & Final Report (Atoka Bank & Heartthrob Battery)
Date: Wednesday, March 1, 2017 2:50:00 PM
Attachments: image001.png
D1_EOG_Atoka Bank and Heartthrob Battery (Form C-141 Initial Final Report 1-10-2017).pdf

Dear Mr. Asher:

Please see the attachment for your records.

Please inspect the liner in question. It is OCD's understanding that all impacted material in the containment has been removed and the liner inspected for integrity. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids. Pictures and a record of the removal of contaminated fill or proper disposal of liquids are strongly encouraged to accompany submission of initial C-141s.

Thanks,

Olivia Yu
Environmental Specialist
NMOCD, District I
Olivia.yu@state.nm.us
575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: Yu, Olivia, EMNRD
Sent: Thursday, February 9, 2017 2:55 PM
To: 'Bob Asher' <Bob_Asher@eogresources.com>
Cc: 'agroves@slo.state.nm.us' <agroves@slo.state.nm.us>
Subject: RE: Form C-141, Initial & Final Report (Atoka Bank & Heartthrob Battery)

Dear Mr. Asher:

Thank you for the notice. This will be processed.

Olivia Yu
Environmental Specialist
NMOCD, District I
Olivia.yu@state.nm.us

575-393-6161 x113

From: Bob Asher [mailto:Bob_Asher@eogresources.com]
Sent: Friday, January 20, 2017 8:12 AM
To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>
Subject: FW: Form C-141, Initial & Final Report (Atoka Bank & Heartthrob Battery)

Thank you.

Robert C. “Bob” Asher
Safety & Environmental Department
EOG Resources, Inc.
Artesia Division Office
EOG Safety Begins With YOUR Safety



From: Bob Asher
Sent: Thursday, January 19, 2017 2:53 PM
To: Kristen.Lynch@state.nm.us; (tomas.oberding@state.nm.us)
Cc: Amber Griffin; Veronica Alvarado
Subject: Form C-141, Initial & Final Report (Atoka Bank & Heartthrob Battery)

Thank you.

Robert C. “Bob” Asher
Safety & Environmental Department
EOG Resources, Inc.
Artesia Division Office
EOG Safety Begins With YOUR Safety



From: Bob Asher
Sent: Wednesday, January 11, 2017 7:24 AM
To: Kristen.Lynch@state.nm.us; (tomas.oberding@state.nm.us)
Cc: Amber Griffin; Chase Settle; Katie Parker; Veronica Alvarado
Subject: Release Notification (Atoka Bank & Heartthrob Battery)

EOG Y Resources, Inc. (formerly Yates Petroleum Corporation) is reporting a release at the following location (1/10/2017, 10:00 AM).

Atoka Bank & Heartthrob Battery
Section 17, T24S-R33E
Lea County, New Mexico

Released: 130 B/PW; Recovered: 129 B/PW.

Cause of the release was from a hole that developed on the 3" water fill line at the heater treater. Vacuum truck(s) and roustabout crews were called to begin recovery of produced water and repairs on the line. **This is a lined battery and the release was contained within the battery.** A Form C-141 with complete information will be submitted.

Thank you.

Robert C. "Bob" Asher
Environmental Supervisor
Safety & Environmental Department
EOG Resources, Inc.
Artesia Division Office
105 S. 4th Street
Artesia, NM 88210
575-748-4217 (Office)
575-365-4021 (Cell)
EOG Safety Begins With YOUR Safety

