

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

<b>OPERATOR</b>		<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company EOG Y Resources, Inc.	OGRID Number 25575	Contact Robert Asher	
Address 104 S. 4 <sup>th</sup> Street		Telephone No. 575-748-1471	
Facility Name Resolute BTO Federal Com #2H		Facility Type Battery	
Surface Owner Federal	Mineral Owner Federal	API No. 30-025-41452	

LOCATION OF RELEASE

Unit Letter G	Section 24	Township 25S	Range 32E	Feet from the 2590	North/South Line North	Feet from the 2200	East/West Line East	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude 32.11621 Longitude 103.62697

NATURE OF RELEASE

Type of Release Produced Water <b>oil</b>	Volume of Release 10 B/O	Volume Recovered 10 B/O
Source of Release Pumping Unit	Date and Hour of Occurrence 1/29/2017; AM	Date and Hour of Discovery 1/29/2017; AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume of Release N/A	
If a Watercourse was Impacted, Describe Fully.*		



**RECEIVED**

By Olivia Yu at 2:52 pm, Mar 01, 2017

Describe Cause of Problem and Remedial Action Taken.\*  
Well surged, overflowing the tank and causing the release (oil came in to fast and was unable to equalize in the other tanks). Vacuum truck(s) were called.

Describe Area Affected and Cleanup Action Taken.\*  
An approximate area of 120'X 60', all contained within the spray lined containment battery. All (100%) of the released oil was recovered using a vacuum truck. Depth to Ground Water: >100' (approximately 325', per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0. Based on all oil recovered and lined containment, EOG Y Resources requests closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Robert Asher		Approved by Environmental Specialist: 	
Title: Environmental Supervisor		Approval Date: 3/1/2017	Expiration Date:
E-mail Address: Robert_Asher@eogresources.com		Conditions of Approval:	
Date: February 3, 2017 Phone: 575-748-4217		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

**REVISED**

7:38 am, Mar 23, 2018

nOY1808227525

Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.

**From:** [Yu, Olivia, EMNRD](#)  
**To:** [Tucker, Shelly](#); [Bob Asher](#)  
**Cc:** [Amber Griffin](#); [Veronica Alvarado](#)  
**Subject:** RE: Form C-141 Initial/Final Report (Resolute BTO Federal Com #2H, 1/22/2017)  
**Date:** Wednesday, March 1, 2017 3:42:00 PM  
**Attachments:** image001.png  
D1\_EOG\_Resolute BTO Federal 2H (Form C-141 InitialFinal Report 01-29-2017).pdf

---

Dear Mr. Asher:

Please see the attachment for your records.

Please inspect the liner in question. It is OCD's understanding that all impacted material in the containment has been removed and the liner inspected for integrity. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids. Pictures and a record of the removal of contaminated fill or proper disposal of liquids are strongly encouraged to accompany submission of initial C-141s.

Thanks,

Olivia Yu  
Environmental Specialist  
NMOCD, District I  
[Olivia.yu@state.nm.us](mailto:Olivia.yu@state.nm.us)  
575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

**From:** Tucker, Shelly [mailto:[stucker@blm.gov](mailto:stucker@blm.gov)]  
**Sent:** Sunday, February 5, 2017 12:18 PM  
**To:** Bob Asher <[Bob\\_Asher@eogresources.com](mailto:Bob_Asher@eogresources.com)>  
**Cc:** Lynch, Kristen, EMNRD <[Kristen.Lynch@state.nm.us](mailto:Kristen.Lynch@state.nm.us)>; Yu, Olivia, EMNRD <[Olivia.Yu@state.nm.us](mailto:Olivia.Yu@state.nm.us)>; Amber Griffin <[Amber\\_Griffin@eogresources.com](mailto:Amber_Griffin@eogresources.com)>; Veronica Alvarado <[Veronica\\_Alvarado@eogresources.com](mailto:Veronica_Alvarado@eogresources.com)>  
**Subject:** Re: Form C-141 Initial/Final Report (Resolute BTO Federal Com #2H, 1/22/2017)

**BLM accepts your initial/final C-141 for this release. Please endure you pressure wash your facility to cleanup residue.**

If you have any questions or concerns, please do not hesitate to contact me.

Sincerely,

*Shelly J Tucker*

Environmental Protection Specialist  
O&G Spill/Release Coordinator

Bureau of Land Management  
620 E. Greene St  
Carlsbad, NM 88220

575.234.5905 - Direct  
575.361.0084 - Cellular  
575.234.6235 - Emergency Spill Number

[stucker@blm.gov](mailto:stucker@blm.gov)

The **BLM acceptance/approval does not** relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. In such an event that the location does not revegetate, or future issues with contaminants are encountered, the operator will be asked to address the issues until the contaminant issues are fully mitigated and the location is successfully reclaimed. In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

**Confidentiality Warning:** This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

On Fri, Feb 3, 2017 at 7:50 PM, Bob Asher <[Bob\\_Asher@eogresources.com](mailto:Bob_Asher@eogresources.com)> wrote:

The Depth to Ground Water is based off of information on the 'ChevronTexaco Trend Map'. The NMOSE website was down and no information was available.

Thank you.

**Robert C. "Bob" Asher**

**Environmental Supervisor**  
**Safety & Environmental Department**  
**EOG Resources, Inc.**  
**Artesia Division Office**

105 S. 4<sup>th</sup> Street  
Artesia, NM 88210  
575-748-4217 (Office)  
575-365-4021 (Cell)

**EOG Safety Begins With YOUR Safety**

