

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC OGRID # 229137	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443	
Facility Name: Pintail 3 Federal #001H	Facility Type: Tank Battery	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-025-40684

LOCATION OF RELEASE

Unit Letter O	Section 03	Township 26S	Range 32E	Feet from the 260	North/South Line South	Feet from the 2290	East/West Line East	County Lea
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude 32.0657692 Longitude -103.6615829

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 163 bbls	Volume Recovered: 161 bbls
Source of Release: Tank	Date and Hour of Occurrence: June 12, 2017 10:00 am	Date and Hour of Discovery: June 12, 2017 10:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Ms. Yu - NMOCD / Ms. Tucker - BLM	
By Whom? Rebecca Haskell	Date and Hour: June 12, 2017 3:59 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

APPROVED

By Olivia Yu at 9:31 am, Apr 04, 2018



Describe Cause of Problem and Remedial Action Taken.*

The one-inch roll line valves on the oil tanks were shut and the roll pump was powered down and out of service. The roll pump suction and discharge lines were however not isolated. The brass check valve on the #1 oil tank failed because of trapped pressure in the line. All valves on the back of the tanks were closed.

Describe Area Affected and Cleanup Action Taken.*

The release occurred within the lined facility. A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Dakota Neel		Approved by Environmental Specialist: 	
Title: HSE Coordinator	Approval Date: 4/4/2018	Expiration Date: xx/xx/xxxx	
E-mail Address: dneel2@concho.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: December 11, 2017	Phone: 575-746-2010		

* Attach Additional Sheets If Necessary

nOY1716731471

From: [Yu, Olivia, EMNRD](#)
To: [Dakota Neel](#); [Price, Henryetta](#)
Cc: [Billings, Bradford, EMNRD](#); [Jim Amos \(jamos@blm.gov\)](mailto:jamos@blm.gov); [Rebecca Haskell](#); [Robert McNeill](#); [Sheldon Hitchcock](#); [Christopher Gray](#); stucker@blm.gov
Subject: RE: (C-141 Final) Pintail 3 Federal #001H 6/12/17 (30-025-40684)
Date: Wednesday, April 4, 2018 9:33:00 AM
Attachments: approved_Pintail 3 Federal #001H Tank Battery Final C-141 6-12-17 (30-025-40684).pdf

Mr. Neel:

The available information indicates **OPERATOR** has met the requirements of 19.15.29 NMAC and no further corrective action is required. NMOCD considers **nOY1716731471** closed. This determination by the Oil Conservation Division does not relieve Operator of responsibility should future information indicate a threat to ground water, surface water, human health, or the environment. Furthermore, it does not relieve Operator of responsibility for compliance with any federal, state, or local laws and/or regulations.

Thanks,

Olivia Yu
Environmental Specialist
NMOCD, District I
Olivia.yu@state.nm.us
575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: Dakota Neel <DNeel2@concho.com>
Sent: Monday, December 11, 2017 11:30 AM
To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>; Price, Henryetta <hprice@blm.gov>
Cc: Billings, Bradford, EMNRD <Bradford.Billings@state.nm.us>; Jim Amos (jamos@blm.gov) <jamos@blm.gov>; Rebecca Haskell <RHaskell@concho.com>; Robert McNeill <RMcNeill@concho.com>; Sheldon Hitchcock <SLHitchcock@concho.com>; Christopher Gray <CGray@concho.com>; stucker@blm.gov
Subject: (C-141 Final) Pintail 3 Federal #001H 6/12/17 (30-025-40684)

Ms. Yu/Ms. Price,

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids. Please see the attached Final C-141 and picture

taken during the final inspection conducted by a COG HSE representative.



From: Rebecca Haskell
Sent: Thursday, June 15, 2017 1:36 PM
To: Olivia Yu (olivia.yu@state.nm.us); stucker@blm.gov
Cc: Oberding, Tomas, EMNRD (Tomas.Oberding@state.nm.us); Jim Amos (jamos@blm.gov)
Subject: (C-141 Initial) Pintail 3 Federal #001H 6/12/17 (30-025-40684)

Ms. Yu / Ms. Tucker,

Attached is an Initial C-141 for your consideration. Please let me know if you have any questions or concern.

Thank You,

Becky Haskell
Senior HSE Coordinator
COG Operating LLC
600 W Illinois Avenue | Midland, TX 79701
Direct: 432-818-2372 | Main: 432.683.7443
Cell: 432-556-5130
rhaskell@concho.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

From: Rebecca Haskell
Sent: Monday, June 12, 2017 4:59 PM
To: Olivia Yu (olivia.yu@state.nm.us); stucker@blm.gov
Cc: Oberding, Tomas, EMNRD (Tomas.Oberding@state.nm.us); Jim Amos (jamos@blm.gov)
Subject: (Notification) Pintail 3 Federal #001H 6/12/17 (30-025-40684)

Ms. Yu / Ms. Tucker,

COG Operating LLC is reporting a release at the Pintail 3 Federal #001H (30-025-40684)
Unit O Section 03 Township 26S Range 32E
The release occurred at approximately 10:00 AM on 6-12-2017.
Estimated Released: Approximately 236 bbls of oil.
Estimated Recovered: Currently in progress

This release occurred within the falcon lined facility. This area is being evaluated and a C-141 will be submitted. If you have any additional questions please feel free to contact me.

Thank you,

Becky Haskell
Senior HSE Coordinator
COG Operating LLC
600 W Illinois Avenue | Midland, TX 79701
Direct: 432-818-2372 | Main: 432.683.7443
Cell: 432-556-5130
rhaskell@concho.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Further, any contract terms proposed or purportedly accepted in this email are not binding and are subject to management's final approval as memorialized in a separate written instrument, excluding electronic correspondence, executed by an authorized representative of COG Operating LLC or its affiliates.