

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company:	COG Operating LLC	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-683-7443
Facility Name:	WEST PEARL 36 STATE #002H	Facility Type:	Tank Battery

Surface Owner:	State	Mineral Owner:		API No.	30-025-40425
----------------	-------	----------------	--	---------	--------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	36	19S	34E	380'	North	330'	West	Lea

Latitude 32.6230812 Longitude 103.5213776

**NATURE OF RELEASE**

Type of Release:	Produced Water	Volume of Release:	7bbls	Volume Recovered:	6bbls
Source of Release:	4" Steel Pipe	Date and Hour of Occurrence:	10-25-2016 10:00 am	Date and Hour of Discovery:	10-25-2016 10:00 am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour:				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

**RECEIVED**

**By Olivia Yu at 3:39 pm, Feb 28, 2017**



Describe Cause of Problem and Remedial Action Taken.\*

4" steel pipe failed due to corrosion. Replaced the joint with a new section of 4" steel pipe.

Describe Area Affected and Cleanup Action Taken.\*

This release occurred within a lined facility. Vacuum trucks were dispatched to remove all freestanding fluids. Concho had the free fluids and any contaminated material inside the lined facility removed. The liner has been cleaned and returned back to normal operations.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:				<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Robert Grubbs Jr.			Approved by Environmental Specialist: 	
Title:	Senior HSE Coordinator			Approval Date:	2/28/2017
E-mail Address:	rgrubbs@concho.com			Expiration Date:	
Date: November 7, 2016	Phone: 432-683-7443			Conditions of Approval:	Attached <input type="checkbox"/>

Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.

\* Attach Additional Sheets If Necessary