

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

| | | |
|--|-------------------------------------|----------|
| Name of Company: COG Operating, LLC (OGRID# 229137) | Contact: Robert McNeill | |
| Address: 600 West Illinois Avenue, Midland TX 79701 | Telephone No.: 432-683-7443 | |
| Facility Name: Jaguar 18 State 2-3 Central Tank Battery | Facility Type: Central Tank Battery | |
| Surface Owner: State | Mineral Owner: State | API No.: |

LOCATION OF RELEASE

| | | | | | | | | |
|------------------|---------------|-----------------|--------------|---------------|------------------|---------------|----------------|---------------|
| Unit Letter O | Section 18 | Township 23S | Range 33E | Feet from the | North/South Line | Feet from the | East/West Line | County Lea |
|------------------|---------------|-----------------|--------------|---------------|------------------|---------------|----------------|---------------|

Latitude: 32.29846282 Longitude: -103.60727508 NAD83

NATURE OF RELEASE

| | | |
|--|--|--|
| Type of Release: Oil | Volume of Release: 16 bbl. | Volume Recovered: 15 bbl. |
| Source of Release: Tank Overflow | Date and Hour of Occurrence: 4/16/2018 10:00am | Date and Hour of Discovery: 4/16/2018 10:00am |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? Olivia Yu-NMOCD Ryan Mann-NMSLO | |
| By Whom? Sheldon Hitchcock | Date and Hour: 4/16/2018 3:25pm | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |

REVISED

9:16 am, Apr 18, 2018

Volume change

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*


A tank overflow was caused by valves being left in the wrong position. The valve position was corrected.

Describe Area Affected and Cleanup Action Taken.*

All of the fluid remained inside of the lined containment. A vacuum truck was dispatched to recover all freestanding fluids. Concho will have the spill area evaluated for any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

| | | | |
|--|---------------------------------------|--|-----------------------------------|
| Signature:  | Approved by Environmental Specialist: | | |
| Printed Name: DeAnn Grant | Approval Date: | | |
| Title: HSE Administrative Assistant | Expiration Date: | | Attached <input type="checkbox"/> |
| E-mail Address: agrant@concho.com | Conditions of Approval: | | |
| Date: April 18, 2018 | Phone: (432) 253-4513 | | |

* Attach Additional Sheets If Necessary