

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC OGRID # 229137	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443	
Facility Name: Pygmy 27 State #001H Tank Battery	Facility Type: Battery	
Surface Owner: Private	Mineral Owner: State	API No. 30-025-40352

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	27	21S	33E	330	North	190	West	Lea

Latitude 32.456254 Longitude -103.568849

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 40 bbls PW	Volume Recovered: 35 bbls PW
Source of Release: Fittings/Connections	Date and Hour of Occurrence: July 14, 2017 8:00 AM	Date and Hour of Discovery: July 14, 2017 8:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Ms. Yu - NMOCD / Ms. Groves - SLO	
By Whom? Dakota Neel	Date and Hour: July 14, 2017 12:11 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By Olivia Yu at 2:11 pm, Jul 21, 2017

Describe Cause of Problem and Remedial Action Taken.*

The release was caused by a hole that developed in the piping on the dump line of the free water knockout. The section of pipe was replaced.

Describe Area Affected and Cleanup Action Taken.*

The release remained on location within the lined facility. A vacuum truck was dispatched to remove all freestanding fluids. Concho will have the spill area sampled to delineate any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Dakota Neel

Approved by Environmental Specialist:

[Signature]

Printed Name: Dakota Neel

Title: HSE Coordinator

Approval Date: 7/21/2017

Expiration Date:

E-mail Address: dneel2@concho.com

Conditions of Approval:

Attached ☐

Date: July 17, 2017, 2017 Phone: 575-746-2010

Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.

nOY1720251270

* Attach Additional Sheets If Necessary