

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC (OGRID #229137)	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443	
Facility Name: Stratojet 31 State Com #003H	Facility Type: Tank Battery	
Surface Owner: Private	Mineral Owner: State	API No. 30-025-40103

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	31	20S	35E	330	South	1,980	West	Lea

Latitude 32.5232162 Longitude -103.4986191 NAD83

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 31 bbl.	Volume Recovered: 30 bbl.
Source of Release: Cracked Fiberglass	Date and Hour of Occurrence: May 6, 2018 5:00pm	Date and Hour of Discovery: May 6, 2018 5:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Olivia Yu- NMOCD, Bradford Billings – NMOCD	
By Whom? Sheldon Hitchcock	Date and Hour: May 7, 2018 7:20am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By Olivia Yu at 9:44 am, May 09, 2018



Describe Cause of Problem and Remedial Action Taken.*

The release was caused by the fiberglass around the swedge cracking. The tank is being repaired.

Describe Area Affected and Cleanup Action Taken.*

The release occurred within the lined facility. A vacuum truck was dispatched to remove all freestanding fluids. Concho will have the spill area evaluated for any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: DeAnn Grant		Approved by Environmental Specialist: 	
Title: HSE Administrative Assistant	Approval Date: 5/9/2018	Expiration Date:	
E-mail Address: agrant@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: May 9, 2018	Phone: 432-253-4513	Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.	

* Attach Additional Sheets If Necessary

nOY1812935128

From: Sheldon Hitchcock
To: [Yu, Olivia, EMNRD](#); [Billings, Bradford, EMNRD](#)
Cc: [Robert McNeill](#); [Rebecca Haskell](#); [Dakota Neel](#); [Christopher Gray](#); [DeAnn Grant](#)
Subject: (Notification) Stratojet 31 State Com #003H (30-025-40103) 5/6/2018
Date: Monday, May 7, 2018 7:20:11 AM

Ms. Yu,

COG Operating, LLC (OGRID# 229137) is reporting a release at the Stratojet 31 State Com #003H Battery

The release occurred on May 6, 2018. All of the fluid remained inside of the lined containment.

Release Location:

ULSTR: N-31-20S-35E

Lat/Long: 32.5232162 -103.4986191

Estimated Volume Released: >25bbls

Estimated Volume Recovered: On going

All of the fluid remained inside of the lined containment. COG will have the release evaluated and will submit an initial C-141. If you have any questions or concerns please do not hesitate to contact me.

Thank you,

Sheldon L. Hitchcock
HSE Coordinator
COG Operating LLC
2407 Pecos Avenue | Artesia, NM 88210
Cell: 575-703-6475 | Office: 575-746-2010
slhitchcock@concho.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please

immediately notify the sender by return email and delete this email from your system. Further, any contract terms proposed or purportedly accepted in this email are not binding and are subject to management's final approval as memorialized in a separate written instrument, excluding electronic correspondence, executed by an authorized representative of COG Operating LLC or its affiliates.