

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating, LLC (OGRID #229137)	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland, TX 79701	Telephone No. 432-683-7443	
Facility Name: Crockett State #002H	Facility Type Tank Battery	
Surface Owner: State	Mineral Owner: State	API No. 30-025-41080

LOCATION OF RELEASE

Unit Letter H	Section 20	Township 21S	Range 33E	Feet from the 2,310	North/South Line North	Feet from the 190	East/West Line East	County Lea
------------------	---------------	-----------------	--------------	------------------------	---------------------------	----------------------	------------------------	---------------

Latitude 32.4652519 Longitude -103.5866699 NAD83

NATURE OF RELEASE

Type of Release Oil & Produced Water	Volume of Release 25 bbl. Oil 100 bbl. Produced Water	Volume Recovered 20 bbl. Oil 90 bbl. Produced Water
Source of Release Tank Overfill	Date and Hour of Occurrence May 20, 2018 11:30pm	Date and Hour of Discovery May 20, 2018 11:30pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
<div>RECEIVED By Olivia Yu at 8:25 am, May 23, 2018</div>		



Describe Cause of Problem and Remedial Action Taken.*

The release was caused by the tanks overfilling.

Describe Area Affected and Cleanup Action Taken.*

The release occurred within the lined facility. A vacuum truck was dispatched to remove all freestanding fluids. Concho will have the spill area evaluated for any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: DeAnn Grant		Approved by Environmental Specialist: 	
Title: HSE Administrative Assistant	Approval Date: 5/23/2018	Expiration Date:	
E-mail Address: agrant@concho.com	Conditions of Approval:		Attached <input checked="" type="checkbox"/>
Date: May 22, 2018	Phone: 432-253-4513		

* Attach Additional Sheets If Necessary

Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.

nOY1814330385