

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	Devon Energy Production Company	Contact	Merle Lewis, Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No.	575-748-3371
Facility Name	Boomslang 14-23 Fed 1H	Facility Type	Oil
Surface Owner	Private	Mineral Owner	Federal
		API No.	30-025-42920

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	14	24S	33E	200'	FNL	1980'	FEL	Lea

Latitude_32.2243153_ Longitude_103.5410047_ NAD83

NATURE OF RELEASE

Type of Release	Volume of Release	Volume Recovered
Natural Gas	152 MCF	0 MCF
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Compressor gasket	May 11, 2018 @ 10:40 PM	May 11, 2018 @ 10:40 PM
Was Immediate Notice Given?	If YES, To Whom?	
<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	N/A	
By Whom?	Date and Hour	
N/A	N/A	
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

RECEIVED

By Olivia Yu at 11:53 am, Jun 01, 2018


Describe Cause of Problem and Remedial Action Taken.*

Main compressors 1 inch big joe regulator on discharge line for supply gas going to blow case blew a gasket. Regulator and discharge line isolated and compressor was shut down.

Describe Area Affected and Cleanup Action Taken.*
Approximately 152 MCF released. 0 MCF recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Sheila Fisher</i>	Approved by Environmental Specialist: 	
Printed Name: Sheila Fisher	Approval Date: 6/1/2018 n Date:	
Title: Field Admin Support	Conditions of Approval:	Attached <input type="checkbox"/>
E-mail Address: Sheila.Fisher@dv.com		
Date: 5/14/18 Phone: 575.748.1829		

* Attach Additional Sheets If Necessary

nOY1815243088

Boomslang 14-23 Fed 1H

152 MCF_5.11.18



This map is for illustrative purposes only and is neither a legally recorded map nor survey and is not intended to be used as one. Devon makes no warranty, representation, or guarantee of any kind regarding this map.

WGS_1984_Web_Mercator_Auxiliary_Sphere
Prepared by: Sheila Fisher
Map is current as of: 14-May-2018



Miles
0 0.01 0.02 0.04 1:1,779

